

**S P E C T R O L A B**

A BOEING COMPANY

**Spectrolab, Inc.**

12500 Gladstone Avenue, Sylmar, CA 91342 USA

FAA Repair Stations No. L9SR877X

EASA Repair Station No. EASA.145.6207

## **SEARCHLIGHT COMPONENT REMOVAL REPORT:**

Date Posted: 1/19/2010

For improved tracking and monitoring of components returned for Repair, we have developed the Searchlight Component Removal Report. Once the Customer completes the report with their Repair specific information, we request that the Removal Report be included with the returned component(s). This information will assist us to thoroughly expedite the Return through the Evaluation and Repair process. The input provided by our Customer's will be valuable in considering the need for any potential product improvements/modifications.

The Searchlight Component Removal Report is available through our website, Distributors and Service Centers, and will be included with each new product shipment. Please visit the "Customer Service" Section in our website for an electronic version.

Please [click here](#) for the form.